
RELAY RACK- SERIES

ASSEMBLY INSTRUCTIONS FOR RRCMD - VERTICAL CABLE MANAGER

BUL10271 REV. A

PAGE 1 OF 1




PARTS LIST		
ITEM No.	DESCRIPTION	QTY
1	CABLE MANAGER	1
2	SCREW 3/8-16 X 3/4 CAP HEX	6
3	NUT 3/8-16 HEX ZP	6
4	WASHER FLAT 3/8" ZP	6





9/16" Open End Wrench





Relay Rack & Cable Manager assembled

ASSEMBLY INSTRUCTIONS:

- A) Line up the back of the cable manager with the back of the relay rack, then lift the cable manager so it is flush with the top of the relay rack. (3 sets of holes should now line up)
- B) Using the hardware supplied, insert 2 3/8-16 x 1" bolts through the cable manager and relay rack at the top then fasten loosely using washer and nut.
- C) Insert the remaining hardware at 2 other points, (center and bottom), fasten loosely.
- D) Ensure that cable manager is sitting square then tighten all bolts.



visit our website @ www.hammondmfg.com